

Product Spotlight

PS010-040124

4/1/2024

Customer Service and Digital Assets

We're ready and available to assist you.

Use our website www.atrobushing.com 24x7x365 or contact our customer service / tech support team at (800) 325-6114 during business hours Monday-Friday to talk with an expert.



Use our website www.atrobushing.com or call (800) 325-6114.

Our website offers fast, easy parts search, detailed product specs, and cross-reference.

SKS14705 - Spiral Kit - K147E

Item	Description
ATRO #	SKS14705
Category	Steering
Description	Spiral Kit - K147E
Shipping Weight	20.44 lbs
UPC Code	751354042061
Contains Bushings	Steel Spiral No Ream Kit
Includes Kit Components	King Pin (2) Spiral Bushing (4) Seal Kit SL147E-CON (1) Shim and Hardware Kit BK147E (1) End Plate EP122E (4) Thrust Bearing BRT188S (2) Lock Pin LP147E-L (2) Lock Pin LP147E-S (2)
Misc. Specs	Axle Repair Sleeve SKAS147E Available for SKS14705 Kit Kingpin=1.872"X9.05" - Double Lock Same Side Fitment: Spicer/Dana/Eaton, 02 Codes, Codes: 14600# 02-AEZ, 02-AGB, 02-AGC, 02-AGE, Spicer/Dana/Eaton, E Codes, Codes: 10000# E1002I/W 12000# E1202I/W , E1321I/W, 13200# E1322I/W 14600# E1462I/W
Install Tool	Long T-Handle=SKT090L, Short T Handle=SKT090S
Misc. Tool	Seal Driver=SKPT147E
Warranty	U.S./Canada 3-Year: Export 1-Year



Detailed CAD product images showing kit components.

Product specifications.

- Kit number
- · Component parts breakdown
- · Spec information
- Tool information

Cross reference and competitor kit information.

- Exact Cross indicators
- Near Cross indicators
- · Application notes

Parts Cross Reference

OEM/Brand	Cross Reference	Application Notes
Automann	460.534E	
Automann	460.534B	
Dana	328349	
Dana	328347	
Dayton Parts	300-305	
Dayton Parts	300-306	
Dayton Parts	306-K147E	Exact Cross Steel No Ream
Eaton	503701	Garlock Bushings
ELGIN	KB868	
Holland	BF868	
Meritor	R202006	Near Cross
Meritor	G200301	
Meritor	G201327	Composite
Meritor	R200301	
Meritor	R201327	
Meritor	R203038	
Spicer	KPK3002	
Stemco	K147E	Exact Cross
Stemco	K147E	
Stemco	50.147.05	
Stemco	70.147.05	