PRODUCT SPOTLIGHT



ATRO BUMPER CHOICES



- Today's typical rubber bumpers do not last very long and may be worn out in six to twelve months.
- ATRO's polyurethane bumpers have been proven to last as much as 15 times longer than rubber.

WASTE HAULER











TRAILER











































- Labor Cost
- Downtime
- Trailer Damage

Changing out a simple trailer bumper can present a technician with unexpected problems. Many of today's bumpers are mounted into a sealed bumper frame that contains the stop/tail/turn lamps. Often, a lamp will need to be removed to gain access to the rusted nuts on the inside of the trailer bumper frame. This is further complicated when the lamp is secured with a riveted lock ring, common with the newer LED powered stop/tail/turn lamps. The bumper removal process usually takes a minimum of 20 minutes and as much as 45 minutes to complete and often the lamp gets damaged in the process.

ATRO BUMPERS

ATRO PARTS ENGINEERED | DURABLE | RELIABLE MANUFACTURED IN ST. CLAIR, MISSOURI | U.S.A.

| ATRO Part Number | Description | OEM Cross Reference | Height | Width | Length | ID | OD | Bolt Hole | Bolt Holes |
|---------------------|--------------------------|--|----------|----------|---------|------|--------|--------------|---------------------|
| BP52-34203 | Trailer/Dock Bumper | Miscellaneous | 3 3/4" | 3" | 6" | | | 1/2" | 3" с-с |
| BP89-65100 | Trailer Bumper | Hyundai HY10046289 Stoughton 04-86997-001-00 | 3 1/8" | 2 15/16" | 5 7/8" | | | 1/2" | 3" с-с |
| BP89-65300 | Trailer/Dock Bumper | Stoughton | 3.725" | 5 1/2" | 7 1/2" | | | | 5 3/8" с-с х 3" с-с |
| BP99-34303 | Trailer Bumper | Great Dane SL3000W James King 3044 | 3 3/8" | 2 3/4" | 5 9/16" | | | 1/2" | 2 1/2" c-c |
| BP99-34312 | Trailer/Dock Bumper | Wabash | 3 1/4" | 2 1/2" | 6" | | | | 2.63" с-с |
| BP99-34408 | Trailer Bumper | Fontaine 50407007 | 2" | 2" | 12" | | | 1/2" | 4 1/2" c−c |
| BP99-34863 | Trailer Door Bumper | Great Dane 42500863 | | | 1.12" | .38" | 1.7" | | |
| BP99-36037 | Trailer Bumper | Miscellaneous | 3.3" | 3" | 6" | | | 1/2" | 2 1/2" c-c |
| BP99-36038 | Trailer Bumper | James King 3043 | 3.2" | 4" | 6.1" | | | 1/2" | 2.4" с-с |
| BP99-36040 | Trailer Bumper | Fontaine B552641 James King 3042 Vangaurd RDB00002 | 1 3/4" | 1 15/16" | 7" | | | 3/8" | 4 1/2" c-c |
| BP99-65000 | Trailer Door Bumper | Freightliner FTG 022 01085 Mack 9817-02201085 Sterling FTG 022 01085 Utility Trailer 3-1250-25 Volvo FLE02201085 | | | 1 5/8" | | 1 7/8" | 1/2" | |
| BP99-65020 | Trailer Bumper | James King 3035 Utility Trailer 03-1250-0-214 | 3 1/2" | 2 5/8" | 4 5/8" | | | 7/16" | 2 3/8" c-c |
| BP99-65040 | Trailer Bumper | James King 3630 Kentucky Trailer T-9000 Utility Trailer RDB-003 Wabash WAB21400098 | 3 3/4" | 3" | 5 3/4" | | | 1/2" | 3 1/2" c-c |
| BP99-650B1 | Door Bumper | James King 3050 | 1" | | | .45" | 2 1/2" | | |
| BP99-65182 | Trailer Bumper | Benson Trailer B52641 Great Dane 035-25182 | 3 1/2" | 2 1/2" | 6 1/4" | | | 1/2" | 3 3/4" |
| BP99-65304 | Trailer Bumper | Great Dane 41700301; 41700304 | 3 1/2" | 2 3/4" | 5 5/8" | | | 1/2" | 2 3/4" c-c |
| BP99-65535 | Bumper/Arm Stop | Heil 01411535 | 2 13/16" | 4 1/2" | 9 7/8" | | | 5/8" | 5" c-c |
| MS99-34008 | Trailer/Dock Bumper | Great Dane 30036; 41700322 | 3 5/8" | 5 1/2" | 8" | | | .775" | 3.4" x 5.5" c-c |
| MS99-65035 | Bumper Pad | McNeilus 0602035 | 3" | 6" | 7 7/8" | | | 1/2" | 5 1/2" x 3" c-c |
| MS99-65038 | Trailer Bumper | McNeilus 0120500 Stoughton 04-85104-PLY-00 | 3 1/2" | 3" | 6" | | | 1/2" | 3" c-c |
| MS99-65045 | Bumper Pad (Severe Duty) | McNeilus 0602035 | 3" | 6" | 7 7/8" | | | 1/2" | 5 1/2" x 3" c-c |
| MS99-69003 | Ladder Bumper | RBR Enterprises 2500393 | 5/8" | | | | 1 1/2" | 3/8" | |
| MS99-69717 | Grabber Assembly Roller | Heil 0620717 McNeilus 1108125 | | | 1 7/16" | 1/2" | 2 1/2" | | |
| MS99-69804 | Roller Gripper | Heil 0620804 tri-cuff Heil 0620805 2 pcs stacked/tricuff | | | 2" | | 2 1/2" | 5/8" | |



POLYURETHANE PARTS | SOLUTIONS FOR HEAVY TRUCKS

ATROBUSHING.COM ©2018 Atro Engineered Systems, Inc. 6 Bolte Lane St. Clair, Missouri 63077 | U.S.A. (800) 325.6114 | Fax (866) 920.2005